

RB T907

CONTROLLED DOCUMENT

CSP-900IPL-4

JUL-2F

~~DEC 15 2015~~

~~JOB NUMBER~~

~~01-16955~~


Job cancel'd
mw

CSP-900IPL-4

JUL-26-1995 15:49

COM'L FIELD SERVICE

ILLUSTRATED PARTS LIST



SHOP COPY

NOTE:
1. MAKE FROM CHIP CHASER, OR ANY 0.020 INCH
(0.508 mm) THICK SPRING STEEL (2 EACH).

UNDER REVIEW

URF 19-1201 19.11.07 (VM)

800--
9P01-034

P.02

P.13

Figure 11. T907 Main Rotor Hub Bearing Removal Tool - Field Fabricated

01-10-00